



U. S. Steel
Clairton Works
400 State Street
Clairton, PA 15025-1855

Proffers

October 15, 1997

Director, Air Toxics and Radiation Division
U. S. EPA Region M
841 Chestnut Street
Philadelphia, PA 19107

SUBJECT: 1997 Summary Report - Leak Detection and
Repair of Equipment in Benzene Service

Dear Sir or Madam:

Enclosed please find two copies of the following benzene NESHAPS Monitoring Report:

- Leak Detection and Repair of Equipment in Benzene Service for the period January 1997 through June 1997.

This report summarizes the results of the monitoring of equipment in benzene service at USS Clairton Works for fugitive emissions. The report has been prepared to satisfy the requirements promulgated by 40 CFR 61 Subparts L and V.

If you have any questions regarding this package, please call me at (412) 233-1101.

Sincerely,

W. B. McCallum

W. B. McCallum

Environmental Control

RECEIVED

OCT 20 1997

AIR, RADIATION & TOXICS
Division



412-578

8103

Westman McCallum

Bill RAUSCH

Bill CLARK

578-8135

Randy YORK
412-233-1114